


THIS DRAWING CONTAINS INFORMATION PROPRIETARY TO RF INDUSTRIES, ANY UNAUTHORIZED USE OF THIS DRAWING IS EXPRESSLY PROHIBITED WITHOUT WRITTEN PERMISSION FROM RF INDUSTRIES. ANY VIOLATION IS PUNISHABLE UNDER U.S. COPYRIGHT LAWS.

ALL DIMENSIONS ARE REFERENCE ONLY


PAR	RFB-1707-S			
Æν	DESCRIPTION	DWN	DATE	APPROVE
_	ENGINEERING RELEASE	czs	09/08/00	JDMc
Α	CHANGED STRIP DIMENSIONS FOR CABLE	JDM	5/1/08	JDMc








SOLDER OR USE CRIMP DIE .042





RECOMMENDED STRIPPING DIMENSIONS

RECOMMENDED CRIMP DIE .178

SPECIFICATIONS:

IMPEDANCE: 75 Ohms

FREQUENCY RANGE: 0-4 GHz

WORKING VOLTAGE: 500 V rms @ sea level TEMPERATURE RANGE: -65°C TO 85°C

INSULATION RESISTANCE: 5k M Ohms min.

FOR RG-161, 179, 179A, 187 & 187A/U CABLE

BREAK ALL CORNERS & EDGES .005 R. MAX.

7610 MIRAMAR RD SAN DIEGO, CA 92126 (858) 549-6340 (858) 549-6345 FAX

DIVISION OF RF INDUSTRIES, LTD.

CHAMFER 1ST & LAST THREADS 45° SURFACE ROUGHNESS 63 FINISH MIL-STD-10 DIAMETERS ON COMMON CENTERS TO BE CONCENTRIC WITHIN .002 T.I.R.

BNC PLUG, CRIMP


75 OHM


SIZE	CABLE GROUP		DWG NO. RFB—170	7-S	R	REV	
SCA	JF: NTS	CAD FI	ILE OUTLINE	SHFFT	1	OF	1

1	SHELL	1	BRASS	NICKEL, 100μ "	008974		UNLESS OTHERV	VISE SPECIFIED:
2	BODY	1	BRASS	NICKEL, 100μ "			1. REMOVE ALL BURR	c
3	INSULATOR	1	PTFE				2. BREAK ALL CORNE	-
4	GASKET	1	RUBBER	RED			3. CHAMFER 1ST & L	AST THREADS 45°
5	RETAINING RING	1	BRASS	NICKEL, 100μ "				SS 63 FINISH MIL-ST
6	SPRING	1	SK5	NICKEL, 100μ "			CONCENTRIC WITHII	MMON CENTERS TO BE
7	WASHER	1	BRASS	NICKEL, 100μ "			6. ALL DIMENSIONS A	
8	PIN	1	BRASS	GOLD, 3μ "				
9	SLEEVE	1	DELRIN					ARE IN INCHES
10	FERRULE	1	BRASS	NICKEL, 100μ "	DRAWN	5/1/08	AND [MILLIN	=
1 1					JDM CHECKED	3/1/06		HERWISE NOTED
12					CHLORED		TOLERANCES	Ī
13					ORJ DRAWN		DECIMALS	DIAMETER
14					C. ZUNIGA	10/16/01	.XXX±.003 [.08]	.XXX±.001 [.03]
#	DESCRIPTION	QTY	MATRL	FINISH	APPROVALS	DATE	.XX±.005 [.13]	.XX±.003 [.08]
#	I DESCRIPTION	וויאן	LIVITINE	1 1141311	I AFFROVALS	DAIL		

CABLE ASSEMBLY INSTRUCTIONS

RFB-1707-S





- Step 1: Cut end of cable evenly. Strip cable to dimensions shown in catalog or on outline drawing. All cuts are to be clean and square. Do not nick braid or center conductor when cutting. Slide ferrule over cable. If using strain relief or heat shrink tubing slide onto cable first.
- Step 2: Pre tin cable conductor if using stranded cable (if needed). Place insert over cable dielectric and under braid. Slide pin onto center conductor until it yields against the cable dielectric. Solder or crimp pin in place. If soldering use minimum amount of heat to avoid damage to the cable insulator.
- Step 3: Slide ferrule stud under braid, while inserting the pin into the body.
- Step 4: Slide the ferrule over the braid until it yields against the back of the connector. Crimp the ferrule with crimp tool as specified on connector drawing. Trim any extra braid extending out of ferrule end.

RFB-1707-S AP.DWG